

# MONUMENT RECORD


Corner I.D. #

E-21

STATE OF INDIANA - COUNTY OF MONROE

Section Thirty, 30, Township 9 North, Range 1 East

**Monument Description & Remarks:** Found 1/2" diameter Rebar, firm in ground,  
at SE corner of section. Rebar marked w/1 1/2" diameter iron pipe, 2.1' out  
of ground. Rebar is 0.4' out of ground w/old flagging.



State of Indiana  
County of Monroe

Space  
Reserved For  
Recording  
Officer

I, Michael W. Friley, County Surveyor, hereby certify  
that this document was prepared under my direction in  
accordance with the provisions of Section 17-3-64-4  
through 17-3-64-8 of the Indiana Code, being Acts of 1965,  
Chapter 319; and the above data is given under my hand and  
seal this 4th day of June, 19 96 A.D.

Indiana Registered Land Surveyor No. \_\_\_\_\_ or

Monroe County Surveyor's Office  
United States Government Agency

Monroe County Surveyor  
Title

Field Book:

96-01

Page:

58